




# MICROCHANNEL COILS

## YORK YLAA & YVAA

USA Coil & Air manufacturers alternative replacement condenser coils for YORK brand chillers, specifically for the YORK YLAA and the YORK YVAA. These replacement coils are designed as near perfect drop-in, with higher quality, longer life. The coils are 82.43" wide x 47.5" tall x 1.5" deep and have copper I.D. solder connections mounting brackets for easy installation.

### KEY FEATURES

- Available from Stock (call) or 5-6 weeks
- Limited Five (5) Year Warranty
- 650 PSI Working Pressure for R410A or R134a Service
- 1-1/8" IDS copper Inlet, 7/8" IDS copper Outlet
- Low Refrigerant Pressure drop for improved performance
- Complete with (4) Mounting Brackets for easy installation
- For Microchannel and Fin/Tube Coil Replacement



Model: WM2-83-4525-407-EC (E-Coated)

### COMPARATIVE ADVANTAGES

- USA Made - High Quality
- Proven Performance and Robust Design
- 100% Factory Leak Tested
- E-coating Protection Standard
- Thicker Tube Walls for Longer Service Life
- Low Flux Manufacturing Method - Provides Lower Corrosion Potential
- Designed to replace FIN/Tube and/or Microchannel Coils for YORK brand Chillers

### QUALITY & CRAFTSMANSHIP

USA Coil & Air replacement coils are designed as an UPGRADE and improvement to the original manufacture's heat exchangers, either Microchannel type or Fin/Tube type. While many OEM's use foreign made or "automotive" quality coils or thin wall fin/tube, USA Coil & Air builds in long life quality. The heat exchanger "Upgrade" feature is due to thicker tube walls, a more robust design to withstand thermal cycling and E-Coating to assure long life corrosion protection.


As a primary supplier to major HVAC & Refrigeration Original Equipment Manufacturers, USA Coil & Air leads the industry in Microchannel coil Design, Quality, and Customer Service.

Have any questions or need any additional information? Feel free to contact us - We are here to help!

USA Coil & Air | Visit us Online at [www.usacoil.com](http://www.usacoil.com) | Contact us today at 800.872.2645

# MICROCHANNEL COILS

## YORK YLAA & YVAA



## INSTALLATION REQUIREMENTS

- Remove existing coil(s) using standard industry practices and in accordance with refrigerant recovery regulations.
- Install new coils. Condenser inlet connection must be at the top, per the drawing. Do not install upside down. Use care to not damage coil face while handling. Mounting will require sheet metal screws to secure coil flange into equipment panels.
- Two existing 3/4" inlet connections must be combined to a single 1-1/8" coil inlet connection for easier piping.
- 7/8" outlet connection to connect to 7/8" coil connection.
- Connect rear receiver line (where applicable) to coil rear 1/2" connection.
- Solder (Braze) copper connections using Silver solder or Phos-Copper method. Use wet rag on Al side of connections to protect the Al/Cu joint from overheating and damage to the Al/Cu joint.
- Replace one or all coils in each compressor circuit. (Replace all factory coils, preferred).
- Leak check all connections. Re-charge the system using the original OEM's recommended refrigerant charge quantity, then adjust using site glass (minimal bubbles) and subcooling at 5F to 10F.
- See USA Coil & Air Installation Guidelines for full details.

Have any questions or need any additional information? Feel free to contact us - We are here to help!

USA Coil & Air | Visit us Online at [www.usacoil.com](http://www.usacoil.com) | Contact us today at 800.872.2645